



PO BX 190, Vinemont AL
35179
PH: Huntsville 256-564-7070
Birmingham 205-981-1707
Cullman 256-739-5117
FAX: 256-739-5118
EMAIL: sales@wefindleaks.net

TAX INVOICE / STATEMENT
ABN:

Invoice # 29502

Job Contact
Brian Pierson

Phone:
205-616-2178

Brian Pierson
SMS
211 Yeager Pkwy Ste B,
Pelham, AL 35124

WORK CARRIED OUT AT: 1640 Lake Cyrus Club Dr, Birmingham, AL 35244, USA

DATE: 20th November 2018	CUST ORDER NO:	JOB NO: 29502
DESCRIPTION	PRICE	
1 Commercial Pool Detection/Gutter Pool-1640 Lake Cyrus Club Dr	\$1,200.00	
3 Commercial Pool Detection/Gutter Pool/Hourly-1640 Lake Cyrus Club Dr	\$525.00	
1 Commercial Pool Repair-1640 Lake Cyrus Club Dr	\$75.00	
	SUBTOTAL	\$1,800.00
		\$0.00
	TOTAL CHARGE	\$1,800.00

WORK COMPLETED:

A complete electronic leak detection was performed on a gunite gutter system pool located at 1640 Lake Cyrus Club Dr, Birmingham, AL 35244. A pressure test was performed on (15) returns, (1) dual main drain, (4) vacuum lines, and (25) gutter lines (could not be tested due to gunite over fittings). A leak was detected on gutter valve above ground at pump and on the drain plug for last filter. Mr. Pierson was present and aware of leak locations. A leak was detected on gutter system fitting deep end left side under ladder. Cross members in fittings had to be removed to be repaired. Pool bond was used for a temporary repair. A test of all fittings, light niches, sumps, and surface of the pool was performed. No leaks were detected in the structure. No other leaks were detected at this time.

TECHNICIAN HAS CARRIED OUT THE ABOVE WORK TO MY SATISFACTION. I HAVE READ AND AGREE TO THE TERMS AND CONDITIONS.

Customers Signature: *Brian Pierson*

REMITTANCE

INVOICE #29502

Payment Options:

I/We understand and agree that the information provided is for the purpose of obtaining credit. We further understand and agree that all monies due to American Leak Detection shall be paid in accordance with the terms stated, (upon completion of service) and agree to pay all reasonable cost of collection, in addition any court cost and / or attorney fees incurred in collection process.

Bank Details

Name:
BSB: Account #:

Customer Name: SMS

Guarantee on Detection/Repairs: All leak locations and detection work is guaranteed for 30 days from date of completion. We will re-test the system or refund detection fee(at our sole option) if reported within the above 30 day period that leak still exists. We will not be liable for any consequential losses.